## **Cleanroom equipment - Station 2**



## **Required equipment:**

- 0.01g precision scale (v, v)
- Mixing/dispensing spatula (v, x)
- Hard rubber roller (typically for ink dispensing) (v, o)
- Anti-slip surface mat (v, o)
- Jig (Metal, Kapton, Tape)
  - Independent vacuum pump (v, x)
- Air brush (v, x)
- Microscope (v, v)
- Multimeter (v, v)
- Microscope mount (v, o)

Metal/Kapton jig being cut in the metal workshop, Tape jig design still being finalized

## **Under discussion:**

- Desk lamp (for workplace illumination)
- Lazy suzan (for better re-adjusting orientation during inspection)
- Vacuum pick-up tool (to replace anti-slip mat)
  - Will require separate vacuum system (lower force)

## **Database – wishlist?**



- Baseplate display redesign:
  - Have key information be visible without horizontal scrolling
  - Hide secondary information in dropdown
- Export checker:
  - Display warning/correction message if exported item has missing information
- Worksheet digitization:
  - Enforcing that database stays in sync with physical inventory
  - Enforcing measurements be performed before worksheet can start
  - Redementary tracking of where plates physically are
  - Will need to restructure database tables (needs Yi-Mu to have full access of DB)